

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/02/2020

Submitted Date:

07/05/2020

Document Number:

700402250**FIELD INSPECTION FORM**

Loc ID 399056 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89418	WELL	DA	08/08/1958	DA	103-40358	HUSKY OIL CO 5	DA

**General Comment:**

A follow up inspection of FIR documents:

- 1) 679702306 dated 12-21-2018
- 2) 692400563 dated 12-29-2018

The following compliance issues are uncompleted:

- 1) Plug well & complete reclamation. Complete by 3-12-2019.

This is a summary of inspection report 7004002250.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**Type Comment: Corrective Action: Date: Overall Good: ☐**Spills:**Type  In Containment: Comment: ☐ Multiple Spills and Releases?**Venting:**Yes/No Comment: Corrective Action: Date: **Flaring:**Type Comment: Corrective Action: Date:

**Inspected Facilities**Facility ID: 89418 Type: WELL API Number: 103-40358 Status: DA Insp. Status: DA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well abandon in 1958 or 1959. Under the cement cap with an ~4" hole, the well bore opens to 8" or 10".

Corrective Action: Consult with NW Area Engineers as to proper Plugging & Abandonment procedures & complete Plugging / Reclamation of identified facilities by 3/12/19.

Date: 03/12/2019

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

**Optical Gas Imaging Survey**Survey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Wind: Light Speed: \_\_\_\_\_ (mph) Direction From: \_\_\_\_\_ Weather: \_\_\_\_\_ Temperature: (F)

Assisting Staff: \_\_\_\_\_ Camera #: \_\_\_\_\_

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
8:40	AM	8:50	AM	Wellhead(s)

Comment: FLIR infrared images and movies acquired. No gas venting observed including in HSM. No gas odor detected.Corrective  
Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700402251	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5190446">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5190446</a>