

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/22/2020

Submitted Date:

06/30/2020

Document Number:

688308065

**FIELD INSPECTION FORM**

Loc ID: 434842    Inspector Name: Sherman, Susan    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10706  
Name of Operator: D90 ENERGY LLC  
Address: 202 TRAVIS STREET #402  
City: HOUSTON    State: TX    Zip: 77002

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Oakes, Kevin	713-227-0391	kevin@d90energy.com	Designated Agent
Wolfe, Stephen		stephen.wolfe@state.co.us	
Spear, Sam	(970) 554-1988	sam@d90energy.com	All Inspections
Silverman, Daniel	713-227-0391	dsilverman@d90energy.com	President

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434841	WELL	SI	11/01/2017	OW	073-06559	BIG SKY 14-11	TA

**General Comment:**

Reinspection, no Form 4 for TA status and no MIT performed per last inspection's CAs.

As Drilled Location    Footages Not Available    Lat/Long: 39.53766/-103.40925. Update on Form 4.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	303-638-6096	Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type	#		corrective date
Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	<input type="text"/>
-----------	----------------------

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 434841 Type: WELL API Number: 073-06559 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: No engine on pumping unit/TA. 3/1/2020 SI production info reported to COGCC database.  
 From last inspection #688305301:  
 SI status reported to COGCC database since Nov 2017. Will require MIT by Nov 2019 if not produced.  
 Currently TA, no engine so 30 days to MIT.  
 Contact COGCC Engineering within 10 days. Date: 08/06/2019

Corrective Action: **COGCC Engineering within 10 days.** Date: 08/06/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402435099	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187970">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187970</a>
688308120	D90 Energy Big Sky 14-11	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187956">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187956</a>