

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/30/2020

Submitted Date:

06/30/2020

Document Number:

699302041

FIELD INSPECTION FORM
 Loc ID 422472 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------------------------------|
| , | | COGCCinspections@anadarko.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|---------|---------------------------|-------------|
| 425952 | TANK BATTERY | AC | 03/31/2011 | | - | NICHOLS TANK BATTERY 10-6 | AC |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | OTHER | | |
| Comment: | Possible leak on Horizontal Heated Separator drain pipe | | |
| Corrective Action: | Comply with 605.d | Date: | 07/15/2020 |
| Type | OTHER | | |
| Comment: | Stained soil under east Horizontal Heated Separator | | |
| Corrective Action: | Comply with Rule 1002..(2).D | Date: | 07/05/2020 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-------------------|-------|--|
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | Ag fence | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | barb wire | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | barb wire | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-------------------------------|-----|-------|-----------------|
| Type: Emission Control Device | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|-----------------------------------|------------|-------|
| Type: Horizontal Heated Separator | # 2 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Ancillary equipment | # 7 | |
| Comment: | automation | |
| Corrective Action: | | Date: |
| Type: Gas Meter Run | # | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Bird Protectors | # 3 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|----------------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | OTHER | PBV FIBERGLASS | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 210 bbl | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|------------------------------------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | shares containment with crude tank | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|----------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

Inspected Facilities

Facility ID: 425952 Type: TANK API Number: - Status: AC Insp. Status: AC

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary On Tuesday 6/30/2020 at approximately 1255 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: right;">Nichols 10-6 tank battery at Location #425952 in Weld County Colorado. While there, I observed a Tank battery. During this inspection the following possible compliance issues were observed: 605.d Mechanical issue: possible leak on eas Horiz.Heated Sep.drain, CA date 7-15-2020. See attached photo 5. 1002..(2).D : stained soil under eas Horiz. Heated Sep. CA date 7-5-2020 see attached photo 4. Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p> | revasr | 06/30/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------|---|
| 402435249 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5188223 |
| 699302042 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5188220 |