

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/30/2020

Submitted Date:

06/30/2020

Document Number:

700402202

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Moran, Rick On-Site Inspection
 315495 _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10654
 Name of Operator: LASSO OIL & GAS LLC
 Address: 3021 RIDGE RD #156
 City: ROCKWALL State: TX Zip: 75032

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230930	WELL	PR	06/01/2018	GW	103-08599	COORS 4-15	PR

General Comment:

A follow up inspection of FIR document 700401229.

The following compliance issues were resolved:
 1) "911" was added to the well head sign.

Additional compliance issues:
 1) Gas leaking at the well. Photos 4 & 5. Complete by 7-30-2020.

This is a summary of inspection report 700402202.

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

						corrective date
Type: Horizontal Heated Separator	# 1					
Comment:						
Corrective Action:				Date:		
Type: Deadman # & Marked	# 4					
Comment:						
Corrective Action:				Date:		
Type: Bird Protectors	# 1					
Comment:						
Corrective Action:				Date:		

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 230930 Type: WELL API Number: 103-08599 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: Fencing Condition:

Comment: No fence present.

Corrective Action

Date: _____

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date: _____

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

