

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402438313

Date Received:  
07/07/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10598  
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC  
Address: 123 ROBERT S KERR AVE  
City: OKLAHOMA CITY State: OK Zip: 73102

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Dylan Mair</u>	<u>817.307.6869</u>	<u>dmair@sandridgeenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689802440  
Inspection Date: 03/26/2019 FIR Submit Date: 04/03/2019 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SANDRIDGE EXPLORATION & PRODUCTION LLC Company Number: 10598  
Address: 123 ROBERT S KERR AVE  
City: OKLAHOMA CITY State: OK Zip: 73102

LOCATION - Location ID: 447512

Location Name: Open Range Number: 18 County: \_\_\_\_\_  
Qtrqr: Lot 4 Sec: 18 Twp: 7N Range: 80W Meridian: 6  
Latitude: 40.571594 Longitude: -106.424475

FACILITY - API Number: 05-057-00 Facility ID: 447512

Facility Name: Open Range Number: 18  
Qtrqr: Lot 4 Sec: 18 Twp: 7N Range: 80W Meridian: 6  
Latitude: 40.571594 Longitude: -106.424475

CORRECTIVE ACTIIONS:

1 CA# 123810

Corrective Action: Comply with Rule 605.a(4) or provide evidence of compliance via FIRR. Date: 04/12/2019

Response: CA COMPLETED Date of Completion: 04/12/2019

Operator Comment: A liner was installed beneath the tank prior to commissioning the facility. Best estimate of timing is 4/12/19. Pictures of tank/liner attached.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 123811

Corrective Action: Comply with Rule 603.f .

Date: 04/12/2019

Response: CA COMPLETED

Date of Completion: 04/12/2019

Operator  
Comment: Location has been cleaned.

COGCC Decision:

COGCC  
Representative:

**3** CA# 123812

Corrective Action: Comply with Rule 603.f .

Date: 04/12/2019

Response: CA COMPLETED

Date of Completion: 04/12/2019

Operator  
Comment: Location has been cleaned.

COGCC Decision:

COGCC  
Representative:

**4** CA# 123813

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 04/12/2019

Response: CA COMPLETED

Date of Completion: 04/12/2019

Operator  
Comment: Frac tanks have been removed.

COGCC Decision:

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: A liner was installed beneath the condensate tank prior to commissioning the facility in 2019. Location was cleaned in 2019. Frac tanks were removed in 2019.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dylan Mair

Signed: \_\_\_\_\_

Title: Production Engineer

Date: 7/7/2020 6:24:30 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402438315	Tank
402438316	Liner

Total Attach: 2 Files