

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/07/2020

Submitted Date:

07/07/2020

Document Number:

699302095**FIELD INSPECTION FORM**Loc ID 327352 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------------------------------|
| , | | COGCCinspections@anadarko.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|---------|----------------------------|-------------|
| 442155 | TANK BATTERY | AC | 06/24/2015 | | - | DOLPH TANK BATTERY 15C-1HZ | AC |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Ag fence | | |
| Corrective Action: | | Date: | |

| | | | |
|-------------------------------|------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Flow Line | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: VRU | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 10 | | |

| | | |
|--|-----|-------|
| Comment: automation, electric panels and transformers | | Date: |
| Corrective Action: | | Date: |
| Type: Gas Meter Run | # 1 | |
| Comment: Card inside of meter house indicates current calibration. | | |
| Corrective Action: | | Date: |
| Type: Horizontal Heated Separator | # 3 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Pig Station | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Compressor | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | PBV FIBERGLASS | | , |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|--------------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) 210 bbl | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--|----------|---------------------|---------------------|-------------|--------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: shares containment with crude tanks | | | | | |
| Corrective Action: | | Date: | | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 4 | 300 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|------|----------|---------------------|---------------------|-------------|

| | | | | | |
|--------------------|----------|-----------------|----------------|----------|-------|
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 442155 Type: TANK API Number: - Status: AC Insp. Status: AC

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary On Tuesday 7/7/2020 at approximately 1201 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Dolph Tank Battery 15C-1HZ at</p> <p>Location #327352 in Weld County Colorado. While there, I observed a Tank Battery. During this inspection no compliance issues were observed: See attached photos. Location is dry, weather is clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p> | revasr | 07/07/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------|---|
| 699302096 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5191854 |