

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/06/2020

Submitted Date:

07/08/2020

Document Number:

688308148**FIELD INSPECTION FORM**Loc ID 427920 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 19160Name of Operator: CONOCO PHILLIPS COMPANYAddress: 925 N ELDRIDGE PARKWAYCity: HOUSTON State: TX Zip: 77079**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Crestone Peak	303-268-3703	cogcc.inspections@crestonepr.com	<a href="#">Watkins Office Phone #</a>
Knutson, Danny	970-309-7510	danny.knutson@crestonepr.com	
ConocoPhillips		COPColoradoReg@conocophillips.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427918	WELL	SI	10/01/2019	OW	005-07178	Tebo 32 3H	SI

**General Comment:**[Routine Inspection](#)[Form 10 is in process: 402310158 10 \(CO\) \(CC\) IN PROCESS 03/16/2020 CONOCO PHILLIPS COMPANY](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	lease sign at gate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-659-7740

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Mechanical conditions: union leak at wellhead that is on the ground (see attached photos).		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	07/29/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date	
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:				Date:	
Type: Flare	# 1				
Comment:					
Corrective Action:				Date:	
Type: Flow Line	# 1				
Comment:					
Corrective Action:				Date:	
Type: VRT	# 1				
Comment:					
Corrective Action:				Date:	
Type: VRU	# 1				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:	-0.13 psi				
Corrective Action:				Date:	
Type: Emission Control Device	# 1				
Comment:	on auto				
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:	electric				
Corrective Action:				Date:	
Type: Bird Protectors	# 3				
Comment:	netting over recirc pump, bird was caught inside tank under netting, inspector got it out, check for holes in netting (see attached photo)				
Corrective Action:				Date:	
Type: Horizontal Heater Treater	# 1				
Comment:					
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	same metal berms a crude oil tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 427918 Type: WELL API Number: 005-07178 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI since 10/1/2020.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688308156	Conoco Phillips Tebo 32 3H	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5192521">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5192521</a>