

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2020

Submitted Date:

07/08/2020

Document Number:

688800748**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Hughes, Jim _____ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214619	WELL	PR		GW	067-06223	CRAIG 1	EI
412103	WELL	PR		GW	067-09732	CRAIG 3	EI
477145	SPILL OR RELEASE	AC	07/06/2020		-	Craig 1	EI

General Comment:

On July 8, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #477145. This release occurred at the BP Craig #1 location. For more information regarding this release, please refer to Initial Spill/Release Report Document #402437606.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Free standing sign near PBV is illegible.			
Corrective Action:	Install sign to comply with Rule 210.d.			Date: 09/08/2020
Type	WELLHEAD			
Comment:	Free standing signs near location entrance.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on location signs.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds present around production equipment and pump jacks.			
Corrective Action:	Comply with Rule 603.f.			Date: 07/22/2020
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Guard fencing and stock panel enclosures around pump jacks.			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Stock panel enclosure around separators, electrical supply equipment, and PBV.			
Corrective Action:				Date:
Equipment:				
Type: Gas Meter Run	# 2			corrective date
Comment:	Within separator buildings.			
Corrective Action:				Date:
Type: Prime Mover	# 2			
Comment:	Electric motors.			

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical supply equipment.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.194646,-107.834783
Comment:	Double walled steel PBV.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	No secondary containment berm present.			
Corrective Action:	Secondary containment is inadequate to contain largest single tank plus sufficient freeboard.			Date: 08/07/2020

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>214619</u>	Type:	<u>WELL</u>	API Number:	<u>067-06223</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>412103</u>	Type:	<u>WELL</u>	API Number:	<u>067-09732</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>477145</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 77

Comment: Please refer to Spill/Release Point ID #477145 for more information regarding this release. Site map attached to initial spill report (Document #402437733) and observations made during this field inspection indicate that the release traveled approximately 300' off of the location.

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 08/07/2020

Reportable: YES

GPS: Lat 37.194643

Long -107.834841

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PITType: Lined: Pit ID: 115461 Lat: 37.192877 Long: -107.832998Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment:

Corrective Action

Submit a Form 27 Site Investigation and Remediation Workplan to close pit. Contact COGCC EPS staff.

Date: 07/17/2020**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action Date: **COGCC Comments**

Comment	User	Date
On July 8, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #477145. This release occurred at the BP Craig #1 location. For more information regarding this release, please refer to Initial Spill/Release Report Document #402437606. During this inspection underground utilities were being marked by an EIS employee. The free standing sign near the PBV is illegible. Weeds are present around the pump jacks and all other equipment on site. Spill/Release Point ID #477145 originated at a double walled steel PBV. There is no containment berm around this PBV. Evidence of flow was observed ~300' to the west of the location.	hughesjo	07/08/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
688800749	Inspection Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5192653