

Inspection Photos

API: 055-06101

Operator: MANZANO LLC

Inspection Date: 7/8/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06101 | Date: 7/8/2020

Inspection Photos



Photo 1. Facing south along the access road, which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 7/8/2020

Inspection Photos



Photo 2. There is a pipe riser that remains along the access road. Approximate Lat/Long:37.473,-105.024.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 7/8/2020

Inspection Photos



Photo 3. Facing south along the access road. The cattle guard remains and is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 7/8/2020

Inspection Photos



Photo 4. Facing south along the access road. Access road has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 7/8/2020

Inspection Photos



Photo 5. Facing southwest toward the location. The location has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 7/8/2020

Inspection Photos



Photo 6. Facing south toward eastern side of the location. There is pipe risers and equipment that remain shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 7/8/2020

Inspection Photos



Photo 7. There are pipe risers and a cement base that remain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 7/8/2020

Inspection Photos



Photo 8. Facing southwest toward the cut slope. There is a shallow depression which appears to be where a pit was located. There is a black plastic pipe extending out of the surface shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 7/8/2020

Inspection Photos



Photo 9. Facing southeast toward the cut slope of the location which is approximately 30 ft. height. Red arrow points to an erosion channel at the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 7/8/2020

Inspection Photos



Photo 10. Facing southwest toward shallow depression which appears to be where a pit was located.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 7/8/2020

Inspection Photos



Photo 11. West side of the location facing east.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 7/8/2020

Inspection Photos



Photo 12. Facing toward northeast corner of the location. There is a soil pile at this side of the location and erosion channel shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 7/8/2020

Inspection Photos



Photo 13. There is a deep gully erosion of the northeast fill slope. Red arrow points to 4.5 ft. shovel to show side of erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 7/8/2020

Inspection Photos



Photo 14. Facing east at the northwest side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 7/8/2020

Inspection Photos



Photo 15. Facing southeast toward the location. The cut slope is approximately 30 ft.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06101 | Date: 7/8/2020