

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/01/2020

Submitted Date:

07/05/2020

Document Number:

700402248

**FIELD INSPECTION FORM**
 Loc ID 396671 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 27900

Name of Operator: EQUITY OIL CO

Address: 1700 BROADWAY STE 2300

City: DENVER State: CO Zip: 80290-

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
CO, Western	303-876-7091	whitingwesternco@whiting.com	Western slope inspections
Thompson, Bud		BLThomps@BLM.gov	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228223	WELL	PA	05/31/1957	DA	103-05041	SULPHUR FALLS GOVT 1-A	PA

**General Comment:**

Follow up inspection to FIR document 679704625 dated 6-26-2019. During that inspection a 3 cubic foot bag attached to the well head filled with gas in 27 minutes.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	P&A marker with lettering "South Sulphur #1" and "Equity Oil Co".		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	YES		
Comment:	Gas leaking out several ~1 mm in diameter holes on top of the P&A marker. Odor detected within 10' of the P&A marker.		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 228223 Type: WELL API Number: 103-05041 Status: PA Insp. Status: PA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: P&A in July 1965.Well has not been properly plugged. Gas is venting from the P&A marker.Corrective Action: Contact COGCC engineering for actions to properly plug the well.

Date: 08/05/2020

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: Corrective Action: Date: 
**Pits:**    ☒ NO SURFACE INDICATION OF PIT
**Attached Documents**
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402437586	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5190424">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5190424</a>
700402249	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5190422">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5190422</a>