

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/06/2020

Submitted Date:

07/06/2020

Document Number:

699102002**FIELD INSPECTION FORM**

Loc ID 432800 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**25 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432799	WELL	PR	11/01/2018	OW	123-37287	Latham O-K-2HNB	PR
432804	WELL	PR	11/01/2018	OW	123-37290	Latham 44-41-2HNB	PR
435840	WELL	PR	11/01/2018	OW	123-38787	Latham O34-K31-2HC	PR
435841	WELL	PR	11/01/2018	OW	123-38788	Latham T-P-2HNB	PR
435842	WELL	PR	11/01/2018	OW	123-38789	Latham T34-P31-2HC	PR
435843	WELL	PR	11/01/2018	OW	123-38790	Latham 34-31-2HNB	PR
435844	WELL	PR	11/01/2018	OW	123-38791	Latham T44-P41-2HC	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Faded placards on 2 totes by the gaslift building need replaced.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	08/31/2020
Type	TANK LABELS/PLACARDS		
Comment:	Signs/placards for the pits "4" of them at the tank battery are not posted.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	08/31/2020

Emergency Contact Number:

Comment: Adequate

Corrective Action: _____ Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment in multiple locations needs to be removed for good housekeeping. See attached photo		
Corrective Action:	Comply with Rule 603.f .	Date:	08/31/2020
Type	TRASH		
Comment:	Trash in multiple locations, needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/31/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbwire		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heater Treater	# 7		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 5		

Comment: 3 Gas pig station, 2 oil line pig station.		Date:	
Corrective Action:		Date:	
Type: VRT	# 1		
Comment:		Date:	
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:		Date:	
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:		Date:	
Corrective Action:		Date:	
Type: Other	# 2		
Comment: Test buildings		Date:	
Corrective Action:		Date:	
Type: Emission Control Device	# 6		
Comment:		Date:	
Corrective Action:		Date:	
Type: Bird Protectors	# 13		
Comment:		Date:	
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment: Appear to be plumbed to surface.		Date:	
Corrective Action:		Date:	
Type: Other	# 1		
Comment: Gas lift building		Date:	
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:		Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	PBV CONCRETE		40.334720,-104.403270
Comment: Maintenance Vault					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	60 BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	2		LVST		,
Comment:	two unused methanol tanks needs to be removed if not being used down by the wells. see attached photos.				
Corrective Action:	Comply with Rule 603.f .				Date: 08/31/2020

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	BV CONCRETE		40.337850,-104.413880
Comment:	Shares containment with crude oil tanks.				
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	60 BBLs				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	BV CONCRETE		40.337450,-104.413930
Comment:	Shares containment with crude oil tanks.				
Corrective Action:					Date:

Paint

Condition					
Other (Content)					

Other (Capacity) 60 BBLs						
Other (Type)						
<u>Berms</u>						
Type	Capacity		Permeability (Wall)		Permeability (Base)	Maintenance
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	500 BBLs	STEEL AST		40.337450,-104.413930	
Comment: Shares containment with crude oil tanks.						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity		Permeability (Wall)		Permeability (Base)	Maintenance
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	STEEL AST		40.337850,-104.413880	
Comment: Shares containment with crude oil tanks.						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity		Permeability (Wall)		Permeability (Base)	Maintenance
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	500 BBLs	STEEL AST		40.337850,-104.413880	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	14	500 BBLs	STEEL AST		40.337450,-104.413930
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	432799	Type:	WELL	API Number:	123-37287	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	432804	Type:	WELL	API Number:	123-37290	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	435840	Type:	WELL	API Number:	123-38787	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	435841	Type:	WELL	API Number:	123-38788	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	435842	Type:	WELL	API Number:	123-38789	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	435843	Type:	WELL	API Number:	123-38790	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	435844	Type:	WELL	API Number:	123-38791	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
COGCC Comments									

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 7/6/20 at approximately 0929hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Latham 34-2 Pad of Bonanza Creek Energy, at Location ID # 432800 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused equipment & unused methanol totes in multiple locations, need to be removed for good housekeeping. Comply with Rule 603.f. With a corrective action date of 8/31/20.</p> <p>Trash in multiple locations, need to be removed for good housekeeping. Comply with Rule 603.f. With a corrective action date of 8/31/20.</p> <p>Missing sign/placard on all 4 pits. Install sign to comply with Rule 210.d. With a corrective action date of 8/31/20.</p> <p>Missing/faded sign/placard on 2 methanol totes. Install sign to comply with Rule 210.d. With a corrective action date of 8/31/20.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing education inspections</p>	burnsa	07/06/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402438185	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5190907
699102003	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5190902