

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/06/2020

Submitted Date:

07/06/2020

Document Number:

699302070**FIELD INSPECTION FORM**

Loc ID 410172 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301698	WELL	PR	04/01/2020	OW	123-30083	FIRESTONE 20-29D	PR
302116	WELL	PR	04/01/2020	OW	123-30236	FIRESTONE V 20-04D	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Ag fence x 4		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		

Comment:		cards inside of both meter houses indicate that calibration is not current.		Date:	10/06/2020
Corrective Action:		Comply with Rule 328/329 measurement of gas/oil.			
Type: Emission Control Device	# 2				
Comment:				Date:	
Corrective Action:					
Type: Bird Protectors	# 6				
Comment:				Date:	
Corrective Action:					
Type: Ancillary equipment	# 10				
Comment:		automation, electric panels and transformers		Date:	
Corrective Action:					
Type: Prime Mover	# 1				
Comment:		electric motor		Date:	
Corrective Action:					
Type: Bradenhead	# 5				
Comment:		all appear to be plumbed to surface		Date:	
Corrective Action:					

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	<100 BBLS	BV CONCRETE		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	50 bbl

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: shares containment with crude tanks					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 301698 Type: WELL API Number: 123-30083 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

Facility ID: 302116 Type: WELL API Number: 123-30236 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Monday 7/6/2020 at approximately 0930 hrs. I, Inspector Robbie Revas,
 Conducted an on-site inspection at a Kerr McGee location:

Firestone V-62N67W 20NENW at

Location #410172 in Weld County Colorado.
 While there, I observed a multi well pad and tank battery.
 During this inspection the following possible compliance issues were observed:
 328/329 Measurement of Oil/Gas: Cards inside of meter houses indicate that calibration is
 not current, CA date 10-6-2020 see photos 10 & 12.
 See attached photos.
 Location is dry, weather is clear.
 A follow up on this site inspection needs to be conducted to ensure the
 Compliance issues have been corrected to comply with COGCC rules.
 Continuing education COGCC Inspection Report Summary.
 This is a summary of inspection report.

revasr

07/06/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402438243	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5190985
699302072	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5190977