

Inspection Photos
Location Name: McElvain Dakota #1
API: 05-067-05373



McElvain Dakota #1 well head. Flow line disconnected at well head.



Pit Facility ID #115631.

Inspection Photos
Location Name: McElvain Dakota #1
API: 05-067-05373



Hand augured boring #1, near the center of the pit area.



Second hand augured boring.

Inspection Photos
Location Name: McElvain Dakota #1
API: 05-067-05373



Unused risers in the foreground.



Hand auguring second boring.