

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /24SWNE

Location ID: 312609




Photo #1525 from NE corner of location




Photo #0973 from inspection #699800918 conducted on 4/15/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /24SWNE

Location ID: 312609




Photo #1526 Tank capacity and contents not legible.



Photo #0974 from inspection #699800918 conducted on 4/15/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /24SWNE

Location ID: 312609



Photo #1527 Multiple places with debris on location.



Photo #0975 from inspection #699800918 conducted on 4/15/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /24SWNE

Location ID: 312609



Photo #1528 Multiple places with debris on location.



Photo #0977 from inspection #699800918 conducted on 4/15/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /24SWNE

Location ID: 312609



Photo #1529 Unused equipment on location.