

Inspection Photos

API: 061-06899

Operator: MCCOY PETROLEUM CORPORATION

Inspection Date: 7/13/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06899 | Date: 7/13/2020

Inspection Photos



Photo 1. Facing north at the beginning of the access road. Gate was locked at the cattle guard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06899 | Date: 7/13/2020

Inspection Photos



Photo 2. Facing north toward the location. Sign is posted at gate of fenced location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06899 | Date: 7/13/2020

Inspection Photos



Photo 3. Facing toward the topsoil pile. The soil is not stabilized and there are signs of erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06899 | Date: 7/13/2020

Inspection Photos



Photo 4. Facing north on topsoil pile. There are undesirable weeds along the soil pile.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06899 | Date: 7/13/2020

Inspection Photos



Photo 5. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06899 | Date: 7/13/2020

Inspection Photos



Photo 6. Facing northeast toward the drilling pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06899 | Date: 7/13/2020

Inspection Photos



Photo 7. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06899 | Date: 7/13/2020

Inspection Photos



Photo 8. Facing toward the backside of the soil pile at eastside of the location. There is wind erosion occurring of the sandy soils which are not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06899 | Date: 7/13/2020

Inspection Photos



Photo 9. The sandy soils have eroded offsite and there is no perimeter erosion controls.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06899 | Date: 7/13/2020

Inspection Photos



Photo 10. East side of the location facing west.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06899 | Date: 7/13/2020