

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2020

Submitted Date:

07/13/2020

Document Number:

696103266**FIELD INSPECTION FORM**Loc ID 332855 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 88265Name of Operator: TIGGES OIL LLCAddress: 12406 WCR 64 1/2City: GREELEY State: CO Zip: 80631**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Tigges, Kenneth	970-396-8381	levi.tigges@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245631	WELL	PA	07/16/2019	OW	123-13426	LOG CABIN 1	PA

General Comment:

This is a PLUGGED & ABANDONED WELL / ABANDONED BATTERY inspection.

Well(s): 1: Plugged & Abandoned | PA.

Battery: Abandoned. ALL equipment has been removed.

Abandoned Battery SE corner GPS coordinates: 40.480767, -104.599697

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	1.) Unused Equipment at Abandoned wellsite. 1: Electrical Panel, 1: Road drag, 2: Deadman anchors. Refer to Rule 603.f. Remove 1: Electrical Panel, 1: Road drag, 2: Deadman anchors from Abandoned wellsite. Comply w/ Rule 603.f. Corrective Action date: 10/11/2020. See photos #1, 3, 4, 5, 6.		
Corrective Action:	Remove 1: Electrical Panel, 1: Road drag, 2: Deadman anchors from Abandoned wellsite. Comply w/ Rule 603.f. Corrective Action date: 10/11/2020. See photos #1, 3, 4, 5, 6.		Date: 10/12/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Pump Jack	# 0		corrective date
Comment:	Plugged & Abandoned PA. Pumpjack removed.		
Corrective Action:			Date:
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 245631 Type: WELL API Number: 123-13426 Status: PA Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 07/13/2020 at approximately 15:28 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: TIGGES OIL LLC Location Name: WPF III-66N64W /18SWSW Location ID: 332855 Well Name: Log Cabin #1 API: 05-123-13426 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.480767, -104.599697</p> <p>During this inspection, the following possible compliance issues were observed. 1.) Unused Equipment at Abandoned wellsite. 1: Electrical Panel, 1: Road drag, 2: Deadman anchors. Refer to Rule 603.f. Remove 1: Electrical Panel, 1: Road drag, 2: Deadman anchors from Abandoned wellsite. Comply w/ Rule 603.f. Corrective Action date: 10/12/2020. See photos #1, 3, 4, 5, 6.</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Well appears to be cut / capped. Form 6 doc. #402123465 indicates plugging, cut/cap date: 07/16/2019. Approved.</p> <p>A follow up on this site inspection will be conducted to ensure compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	07/13/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402442638	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5195329
696103267	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5195328