

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/13/2020

Submitted Date:

07/14/2020

Document Number:

688800752

FIELD INSPECTION FORM

Loc ID 306935 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10464
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC
Address: 1801 BROADWAY #1000
City: DENVER State: CO Zip: 80202

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Roy, Catherine		catherine.roy@state.co.us	
Inspections, All		inspections@catamountep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280223	WELL	PR	05/01/2014	GW	067-09073	IGS 405	EI

General Comment:

On July 13, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Catamount Energy Partners LLC IGS #405. For the most recent field inspection report of this facility, please refer to document #693901853.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	AST is labeled with contents, capacity, and has NFPA placard.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Hoses and pipe fittings near meter run and separator.		
Corrective Action:	Comply with Rule 603.f.		Date: 07/29/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Post and wire fencing around perimeter of secondary containment berm.		
Corrective Action:			Date:
Equipment:			
Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	Only two anchors have markers.		

Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		37.091774,-107.774552
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 280223 Type: WELL API Number: 067-09073 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: [Per phone conversation with COGCC Reclamation Specialist on 7/13/20, corrective action regarding pit closure was mistakenly included on Inspection Document #693901853. There is no permitted pit associated with this location, and no surface indication of a pit was observed during this inspection.](#)

Corrective Action: _____

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On July 13, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Catamount Energy Partners LLC IGS #405. For the most recent field inspection report of this facility, please refer to document #693901853. Envirotech and Catamount representatives were on site during this inspection. Per phone conversation with COGCC Reclamation Specialist on 7/13/20, corrective action regarding pit closure was mistakenly included on Inspection Document #693901853. There is no permitted pit associated with this location, and no surface indication of a pit was observed during this inspection.	hughesjo	07/14/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402442975	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5195740
688800753	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5195737