

## Inspection Photos

Location Name: SLUGGER NO. 11 & SLUGGER NO. 1

API#: 05-067-09751 & 067-08985

INSP. #: 695102992



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN/ 911 NOT LISTED AS EMERGENCY CALL NUMBER ON BATTERY SIGN. **INSTALL SIGN TO COMPLY WITH RULE 210.b. CA DATE 10-21-20.**

## Inspection Photos

Location Name: SLUGGER NO. 11 & SLUGGER NO. 1

API#: 05-067-09751 & 067-08985

INSP. #: 695102992



**PHOTO 3: WELL SIGN/ 911 NOT LISTED AS EMERGENCY CALL NUMBER ON BATTERY SIGN. **INSTALL SIGN TO COMPLY WITH RULE 210.b. CA DATE 10-21-20.****

**PHOTO 4: SLUGGER NO. 11 TANK BATTERY**

## Inspection Photos

Location Name: SLUGGER NO. 11 & SLUGGER NO. 1

API#: 05-067-09751 & 067-08985

INSP. #: 695102992



**PHOTO 5: SLUGGER NO. 1 TANK BATTERY**

**PHOTO 6: NOXIOUS WEEDS ON THE OUTER PERIMETER OF LOCATION. REMOVE WEEDS IN ACCORDANCE WITH RULE 603.f. CA DATE 8-10-20.**

## Inspection Photos

Location Name: SLUGGER NO. 11 & SLUGGER NO. 1

API#: 05-067-09751 & 067-08985

INSP. #: 695102992



**PHOTO 7: MORE IMAGES OF NOXIOUS WEEDS. SEE PREVIOUS PHOTO FOR CORRECTIVE ACTION.**

**PHOTO 8: MORE IMAGES OF NOXIOUS WEEDS. SEE PHOTO 6 FOR CORRECTIVE ACTION.**

## Inspection Photos

Location Name: SLUGGER NO. 11 & SLUGGER NO. 1

API#: 05-067-09751 & 067-08985

INSP. #: 695102992



Colorado Oil & Gas Conservation Commission  
37.10808, -107.75423, 2020.0m, 201°  
2020/07/21 11:07:18



Colorado Oil & Gas Conservation Commission  
37.10772, -107.75407, 2013.0m, 130°  
2020/07/21 11:14:59

**PHOTO 9: NO ANCHOR MARKER ON ANCHOR IN FRONT OF SLUGGER NO. 11 WELLHEAD. Install proper guy line markers per Rule 1003.a CA DATE 10-21-20.**

**PHOTO 10: NO ANCHOR MARKER ON ANCHOR IN FRONT OF SLUGGER NO. 1 WELLHEAD. Install proper guy line markers per Rule 1003.a CA DATE 10-21-20.**

## Inspection Photos

Location Name: SLUGGER NO. 11 & SLUGGER NO. 1

API#: 05-067-09751 & 067-08985

INSP. #: 695102992



**PHOTO 11: AREA OF IMPACTED SOIL AROUND SLUGGER NO. 11 WELLHEAD. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 10-21-20.**

**PHOTO 12: NO ANCHOR MARKER ON ANCHOR NEAR SLUGGER NO. 1 TANK BATTERY. Install proper guy line markers per Rule 1003.a CA DATE 10-21-20.**

## Inspection Photos

Location Name: SLUGGER NO. 11 & SLUGGER NO. 1

API#: 05-067-09751 & 067-08985

INSP. #: 695102992



**PHOTO 13: TRASH ON LOCATION (5 GAL. BUCKET).  
REMOVE ALL TRASH ON AND AROUND LOCATION  
COMPLY WITH RULE 603.f. CA DATE 10-21-20.**

**PHOTO 14: TRASH ON LOCATION (NEAR SLUGGER NO.1  
PUMP JACK ENGINE). REMOVE ALL TRASH ON AND AROUND  
LOCATION COMPLY WITH RULE 603.f. CA DATE 10-21-20.**

## Inspection Photos

Location Name: SLUGGER NO. 11 & SLUGGER NO. 1

API#: 05-067-09751 & 067-08985

INSP. #: 695102992



**PHOTO 15: TRASH ON LOCATION (IN FRONT OF SLUGGER NO.1 WELLHEAD). REMOVE ALL TRASH ON AND AROUND LOCATION COMPLY WITH RULE 603.f. CA DATE 10-21-20.**

**PHOTO 16: UNUSED EQUIPMENT STORED ON LOCATION (T POSTS). REMOVE ALL UNUSED EQUIPMENT FROM LOCATION COMPLY WITH RULE 603.f. CA DATE 10-21-20.**

## Inspection Photos

Location Name: SLUGGER NO. 11 & SLUGGER NO. 1

API#: 05-067-09751 & 067-08985

INSP. #: 695102992



**PHOTO 17: UNUSED EQUIPMENT STORED ON LOCATION (UNUSED RISER). REMOVE ALL UNUSED EQUIPMENT FROM LOCATION COMPLY WITH RULE 603.f. CA DATE 10-21-20.**

**PHOTO 18: UNUSED EQUIPMENT STORED ON LOCATION (UNUSED RISERS). REMOVE ALL UNUSED EQUIPMENT FROM LOCATION COMPLY WITH RULE 603.f. CA DATE 10-21-20.**

## Inspection Photos

Location Name: SLUGGER NO. 11 & SLUGGER NO. 1

API#: 05-067-09751 & 067-08985

INSP. #: 695102992



**PHOTO 19: UNUSED EQUIPMENT STORED ON LOCATION (UNUSED RISER). REMOVE ALL UNUSED EQUIPMENT FROM LOCATION COMPLY WITH RULE 603.f. CA DATE 10-21-20.**

**PHOTO 20: IMPROPER OPERATOR NAME ON PRODUCED WATER TANK IN SLUGGER NO. 11 TANK BATTERY. Install sign to comply with Rule 210.b. CA DATE 10-21-20.**

## Inspection Photos

Location Name: SLUGGER NO. 11 & SLUGGER NO. 1

API#: 05-067-09751 & 067-08985

INSP. #: 695102992



**PHOTO 21: AREA OF IMPACTED SOIL NEAR SLUGGER NO. 1 PUMP JACK MOTOR APPEARS TO BE OIL FROM LEAKING MOTOR. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. CA DATE 10-21-20.**

**PHOTO 22: AREA OF IMPACTED SOIL NEAR SLUGGER NO. 11 PUMP JACK MOTOR APPEARS TO BE OIL FROM LEAKING MOTOR. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. CA DATE 10-21-20.**