

**Inspection Photos**  
**Location Name: Fredrick State TB 2-36**  
**Location ID: 332928**




**Photo 1 TB signs**



**Photo 2 TB**

**Inspection Photos**  
**Location Name: Fredrick State TB 2-36**  
**Location ID: 332928**



**Photo 3 ECD**



**Photo 4 Horizontal Heated Separators**



Inspection Photos  
Location Name: Fredrick State TB 2-36  
Location ID: 332928




Photo 5 flow lines




Photo 6 flow lines

**Inspection Photos**  
**Location Name: Fredrick State TB 2-36**  
**Location ID: 332928**




**Photo 7 Unused Gas Meter Run appears to be not connected to production lines**



**Photo 8 Gas Meter Run**



**Location ID: 332928**



**Photo 9 card in meter box indicates current calibration**



**Photo 10 unused equipment on loc.**

**Inspection Photos**  
**Location Name: Fredrick State TB 2-36**  
**Location ID: 332928**



**Photo 11 unused equipment on loc.**



**Photo 12 unused equipment on loc.**

**Inspection Photos**  
**Location Name: Fredrick State TB 2-36**  
**Location ID: 332928**



**Photo 13 unused equipment on loc.**