

**Inspection Photos**  
**Location Name: Carl A. Miller A #4**  
**Location ID: 31365**



**Photo 1 WH sign faded will need replaced in the near future**

**Photo 2 WH**

**Inspection Photos**  
**Location Name: Carl A. Miller A #4**  
**Location ID: 31365**



**Photo 3 pump jack**



**Photo 4 Weeds growing along access road**

**Inspection Photos**  
**Location Name: Carl A. Miller A #4**  
**Location ID: 31365**



**Photo 5 leaking plug on pump jack gear box**



**Photo 6 Stained soil in pump jack base**