

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/21/2020

Submitted Date:

07/21/2020

Document Number:

695102992

FIELD INSPECTION FORM

Loc ID 333801 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 74650Name of Operator: RIM OPERATING INCAddress: 5 INVERNESS DRIVE EASTCity: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments7 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|---------------------------------|---------------------------------|
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| KRYSTEN | | krysten@advancedwirelessllc.com | All Inspections |
| Labowskie, Steve | | steve.labowskie@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 274482 | WELL | PR | 08/01/2018 | GW | 067-08985 | SLUGGER 1 | PR |
| 412373 | WELL | PR | 06/02/2010 | GW | 067-09751 | SLUGGER 11 | PR |

General Comment:

| Location | | | |
|---|---|--------|-------------|
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | WELL SIGN/ 911 NOT LISTED AS EMERGENCY CALL NUMBER ON BATTERY SIGN. WELL SIGN/ 911 NOT LISTED AS EMERGENCY CALL NUMBER ON BATTERY SIGN. INSTALL SIGN TO COMPLY WITH RULE210.b. CA DATE 10-21-20. | | |
| Corrective Action: | INSTALL SIGN TO COMPLY WITH RULE210.b. | Date: | 10/21/2020 |
| Emergency Contact Number: | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: _____ |
| Good Housekeeping: | | | |
| Type | TRASH | | |
| Comment: | PHOTO 13: TRASH ON LOCATION (5 GAL. BUCKET). PHOTO 14: TRASH ON LOCATION (NEAR SLUGGER NO.1 PUMP JACK ENGINE). PHOTO 15: TRASH ON LOCATION (IN FRONT OF SLUGGER NO.1 WELLHEAD). | | |
| Corrective Action: | REMOVE ALL TRASH ON AND AROUND LOCATION COMPLY WITH RULE603.f. | Date: | 10/21/2020 |
| Type | UNUSED EQUIPMENT | | |
| Comment: | PHOTO 16: UNUSED EQUIPMENT STORED ON LOCATION (T POSTS). PHOTO 17: UNUSED EQUIPMENT STORED ON LOCATION (UNUSED RISER). PHOTO 18: UNUSED EQUIPMENT STORED ON LOCATION (UNUSED RISERS). PHOTO 19: UNUSED EQUIPMENT STORED ON LOCATION (UNUSED RISER). | | |
| Corrective Action: | REMOVE ALL UNUSED EQUIPMENT FROM LOCATION COMPLY WITH RULE 603.f. | Date: | 10/21/2020 |
| Type | OTHER | | |
| Comment: | PHOTO 11: AREA OF IMPACTED SOIL AROUND SLUGGER NO.11 WELLHEAD. PHOTO 12: NO ANCHOR MARKER ON ANCHOR NEAR SLUGGER NO. 1 TANK BATTERY. | | |
| Corrective Action: | Conduct maintenance on equipment, cleanup stained material and review self inspection processes. | Date: | 10/21/2020 |
| Type | OTHER | | |
| Comment: | PHOTO 21: AREA OF IMPACTED SOIL NEAR SLUGGER NO.1 PUMP JACK MOTOR APPEARS TO BE OIL FROM LEAKING MOTOR. PHOTO 22: AREA OF IMPACTED SOIL NEAR SLUGGER NO. 11 PUMP JACK MOTOR APPEARS TO BE OIL FROM LEAKING MOTOR. | | |
| Corrective Action: | Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. | Date: | 10/21/2020 |
| Type | WEEDS | | |
| Comment: | PHOTO 6, 7 & 8: NOXIOUS WEEKS ON THE OUTER PERIMETER OF LOCATION | | |
| Corrective Action: | REMOVE WEEKS IN ACCORDANCE WITH RULE 603.f. | Date: | 10/21/2020 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|---------------------------|-------|--|
| Type | TANK BATTERY | | |
| Comment: | around both tank batterys | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|---------------------|--|-------|-----------------|
| Type: Bradenhead | # 2 | | corrective date |
| Comment: | both are plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 2 | | |
| Comment: | BOTH CAL. logs INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR. | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|-----------|----------|---------|------------------|
| PRODUCED WATER | 1 | <100 BBLS | BV STEEL | | |
| Comment: | PHOTO 20: IMPROPER OPERATOR NAME ON PRODUCED WATER TANK IN SLUGGER NO. 11 TANK BATTERY. | | | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | | | | Date: 10/21/2020 |

Paint

| | |
|------------------|--------|
| Condition | |
| Other (Content) | |
| Other (Capacity) | 95 BBL |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 274482 Type: WELL API Number: 067-08985 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 412373 Type: WELL API Number: 067-09751 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 695102993 | INSPECTION PHOTOS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205335 |