

FORM  
INSPRev  
X/15State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/22/2020

Submitted Date:

07/22/2020

Document Number:

699302169

## FIELD INSPECTION FORM

Loc ID 319409 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418860	WELL	SI	02/01/2019	OW	123-32039	BADDING 13-35	SI
418862	WELL	PR	08/01/2018	OW	123-32040	BADDING 12-35SX	SI
418863	WELL	SI	04/01/2020	OW	123-32041	BADDING 13-35SX	SI
418865	WELL	PR	05/01/2018	OW	123-32042	BADDING 11-35SX	SI
418868	WELL	SI	02/01/2019	OW	123-32045	BADDING 12-35	SI
418869	WELL	SI	02/01/2019	OW	123-32046	BADDING 22-35	SI
418871	WELL	PR	05/01/2018	OG	123-32048	BADDING 14-35SX	SI
418905	WELL	SI	02/01/2019	OW	123-32064	BADDING 34-35	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate x 8		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>		
Type	OTHER	
Comment:	Stained soil around the Badding 14 35SX WH.	
Corrective Action:	Comply with Rule 907.e	Date: 08/06/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>		
Type	WELLHEAD	
Comment:	Ag fence	
Corrective Action:		Date:
Type	PUMP JACK	
Comment:	Cow panel x 4	
Corrective Action:		Date:

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 8		
Comment:	all appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 9		
Comment:	Electric panels, transformers and automation.		
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 4		
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 4		
Comment:	electric motors		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:
Type: VRU	# 1		
Comment:			
Corrective Action:			Date:
Type: LACT	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	

PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)	210 bbl					
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:	shares containment with crude tank					
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**

Facility ID: 418860 Type: WELL API Number: 123-32039 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI since 2-1-2019, Form 42 Doc # 402359593 submitted on 4-2-2020 and is approved.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418862 Type: WELL API Number: 123-32040 Status: PR Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI since 1-1-2019, Form 42 Doc # 402359599 submitted on 4-2-2020 and is approved.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418863 Type: WELL API Number: 123-32041 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI since 2-1-2019.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418865 Type: WELL API Number: 123-32042 Status: PR Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI since 12-1-2019, Form 42 Doc # 402359610 submitted on 4-2-2020 and is approved.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418868 Type: WELL API Number: 123-32045 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI since 2-1-2019, Form 42 Doc # 402359602 submitted on 4-2-2020 and is approved.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418869 Type: WELL API Number: 123-32046 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI since 2-1-2019, Form 42 Doc # 402359579 submitted on 4-2-2020 and is approved.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418871 Type: WELL API Number: 123-32048 Status: PR Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI since 7-1-2019, Form 42 Doc # 402359583 submitted on 4-2-2020 and is approved.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 418905 Type: WELL API Number: 123-32064 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI since 2-1-2019, Form 42 Doc # 402359571 submitted on 4-2-2020 and is approved.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 7/22/2020 at approximately 1045 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Badding 14-35SX at Location</p> <p>#319409 in Weld County Colorado.</p> <p>While there, I observed a multi-well pad. Badding 13-35: SI since 2-1-2019, Form 42 Doc # 402359593 submitted on 4-2-2020 and is approved. Badding 12-35SX: SI since 1-1-2019, Form 42 Doc # 402359599 submitted on 4-2-2020 and is approved. Badding 13-35SX: SI since 4-1-2019. Badding 11-35SX: SI since 12-1-2019, Form 42 Doc # 402359610 submitted on 4-2-2020 and is approved. Badding 12-35: SI since 2-1-2019, Form 42 Doc # 402359602 submitted on 4-2-2020 and is approved. Badding 22-35: SI since 2-1-2019, Form 42 Doc # 402359579 submitted on 4-2-2020 and is approved. Badding 14-35SX: SI since 7-1-2019, Form 42 Doc # 402359583 submitted on 4-2-2020 and is approved. Badding 34-35: SI since 2-1-2019, Form 42 Doc # 402359571 submitted on 4-2-2020 and is approved.</p> <p>During this inspection the following possible compliance issue was observed:</p> <p>907.e Housekeeping: Stained soil around the Badding 14-35SX WH, CA date 8-6-2020 See photos 2 &amp; 3.</p> <p>See attached photo #.</p> <p>Location is dry, weather is clear.</p> <p>I spoke with (Name &amp; Title) (Company) what was discussed.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	07/22/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699302170	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205371">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205371</a>