

# Inspection Photos

API: 061-06882

Operator: CHESAPEAKE OPERATING LLC

Inspection Date: 7/13/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06882 | Date: 7/13/2020

## Inspection Photos



### Photo 1.

Facing west at the beginning of the access road. The access road, gate, and cattle guard remains per approved variance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06882 | Date: 7/13/2020

## Inspection Photos



**Photo 2.** Facing east along the two track access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06882 | Date: 7/13/2020

## Inspection Photos



**Photo 3.** Facing northwest toward the location. This area of the location has not established vegetation and is not recontoured.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06882 | Date: 7/13/2020

## Inspection Photos



**Photo 4.** Facing west at the south side of the location. The area outlined has not been contoured and vegetation has not established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06882 | Date: 7/13/2020

## Inspection Photos



**Photo 5.** Facing northwest at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06882 | Date: 7/13/2020

## Inspection Photos



**Photo 6.** Northeast side of the location facing west. This area does not have adequate vegetation growth which is approximately 300 ft. x 100ft.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06882 | Date: 7/13/2020

## Inspection Photos



**Photo 7.** Northwest side of the location facing east. This area does not have adequate vegetation growth which is approximately 300 ft. x 100ft.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06882 | Date: 7/13/2020

## Inspection Photos



**Photo 8.** Northwest side of the location facing south. This area does not have adequate vegetation growth which is approximately 300 ft. x 70ft.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06882 | Date: 7/13/2020

## Inspection Photos



**Photo 9.** Facing northeast toward the location. Vegetation has established in the center of the location. However, the perimeter area of the location has not established vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06882 | Date: 7/13/2020

## Inspection Photos



**Photo 10.** Southwest side of the location facing east. This area does not have adequate vegetation growth which is approximately 300 ft. x 40ft.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06882 | Date: 7/13/2020

## Inspection Photos



**Photo 11.** Facing south toward the surrounding undisturbed reference area, which consists of Blue grama grassland and shrubland.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06882 | Date: 7/13/2020