

Final Reclamation Inspection

July 24, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 327954

Inspection Document #: 697501785

Weld County, CO

NENW Section 14 T5N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MYERS #14-21
Location ID: 327954



Photo 1. Google Earth aerial imagery taken September 7, 2016 illustrating the well location (red circle) and production facility during active operations.

Inspection Photos
Location Name: MYERS #14-21
Location ID: 327954



Photo 2. Google Earth aerial imagery taken July 17, 2019.

This complaint is in regards to an approximate area (red polygon) where soil material was added due to subsidence. Complainant believes the soil material added is poor quality soil.



Photo 3. Photo taken from the western area of subsidence, facing East. Photo illustrates Operator has added soil material to correct subsidence, tilled the added soil material, and recontoured the area. Complainant indicated that poor quality soil was added.

The arrows highlight areas of questionable soil material. The questionable soil material appears to have a high silt content which does not appear to be consistent with reference soils.

Inspection Photos
Location Name: MYERS #14-21
Location ID: 327954



Photo 4. Close up photo taken from the questionable soil material which appears to have a high silt content, facing East.



Photo 5. Close up photo taken from the questionable soil material which appears to have a high silt content.



Photo 6. Close up photo taken from the questionable soil material which appears to have a high silt content.

Inspection Photos
Location Name: MYERS #14-21
Location ID: 327954



Photo 7. Reference photo taken north of the disturbance area, facing West. Photo illustrates the surface owner has converted to alfalfa crop production.