

Inspected Facilities

Facility ID: 431610 Type: PIT API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Water Fresh Lined: _____ Pit ID: 431610 Lat: 40.554022 Long: -104.125733

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: Pit has been backfilled, graded and seeded, Remediation #13218 has been resolved and Pit ID 431610 changed to "CL" status; Weeds are growing in pit reclamation area. Weeds are present within reclaimed pit area.

Corrective Action Control weeds per Rules 603.f. and 1003.f.

Date: 08/27/2020

Permit:	Facility ID	Permit Num	Expiration Date
	431610	1642076	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700529	Former Pit looking northwest	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5211486
693700530	Former Pit looking west	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5211487