

Inspected Facilities

Facility ID: 447926 Type: PIT API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Water Fresh Lined: Pit ID: 447926 Lat: 40.699847 Long: -104.154586

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: Pit has been backfilled, graded and seeded, Remediation 13238 has been resolved and Pit ID 447926 has been changed to "CL". Weeds are present on location and desirable vegetation growth is lacking

Corrective Action Control weeds per Rules 603.f. and 1003.f. Monitor reclamation progress

Date: 08/27/2020

Permit:	Facility ID	Permit Num	Expiration Date
	447926	401074341	
	447926	401074341	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700541	Former Pit looking east	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5211494
693700542	Former Pit looking northeast	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5211495