

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/20/2020

Submitted Date:

07/20/2020

Document Number:

689704975

**FIELD INSPECTION FORM**

Loc ID 335113	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 15 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: 10433 Name of Operator: LARAMIE ENERGY LLC Address: 1401 SEVENTEENTH STREET #1401 City: DENVER State: CO Zip: 80202				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Trujillo, Aaron		aaron.trujillo@state.co.us	
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275241	WELL	PR	10/09/2006	GW	045-13497	CASCADE CREEK 632-13-22	PR
282426	WELL	PR	06/06/2007	GW	045-11766	CASCADE CREEK 697-32-12D	PR
282427	WELL	PR	05/17/2007	GW	045-11767	CASCADE CREEK 697-29-59D	PR
282428	WELL	PR	05/17/2007	GW	045-11768	CASCADE CREEK 697-29-60D	PR
282429	WELL	PR	03/02/2016	GW	045-11769	CASCADE CREEK 697-32-09D	PR
282430	WELL	PR	06/01/2008	GW	045-11770	CASCADE CREEK 697-32-18D	PR
288549	WELL	PR	05/19/2010	GW	045-13290	CASCADE CREEK 697-32-10D	PR
288553	WELL	PR	05/17/2007	GW	045-13291	CASCADE CREEK 697-32-01D	PR
288554	WELL	PR	05/17/2007	GW	045-13292	CASCADE CREEK 697-32-03D	PR

**General Comment:**

Follow Up Field inspection

I, Inspector Mike Longworth, conducted a follow up field inspection.

Storm water corrective action has not been addressed from 07/31/2019 Inspection # 689703420

Subsidence of unstable cut slope behind tank battery.

Install or repair required BMPs per Rule 1002.f.

C.A. Date 08/31/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Danger sign and poly line have been addressed from 07/31/2019 Inspection # 689703420

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Danger sign addressed from 07/31/2019 Inspection # 689703420		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 242-1234

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Poly line addressed from 07/31/2019 Inspection # 689703420		
Corrective Action:		Date:	

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	275241	Type:	WELL	API Number:	045-13497	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282426	Type:	WELL	API Number:	045-11766	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282427	Type:	WELL	API Number:	045-11767	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282428	Type:	WELL	API Number:	045-11768	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282429	Type:	WELL	API Number:	045-11769	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	282430	Type:	WELL	API Number:	045-11770	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	288549	Type:	WELL	API Number:	045-13290	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	288553	Type:	WELL	API Number:	045-13291	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID:	288554	Type:	WELL	API Number:	045-13292	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing well

Corrective Action:		Date:	
--------------------	--	-------	--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Subsidence of unstable cut slope behind tank battery.Corrective Action: Install or repair required BMPs per Rule 1002.f.Date: 08/31/2019**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402446960	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5200027">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5200027</a>
689704976	Inspection 689704975 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5200025">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5200025</a>