

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/21/2020

Submitted Date:

07/21/2020

Document Number:

697001682**FIELD INSPECTION FORM**Loc ID 318189 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 52530Name of Operator: MAGPIE OPERATING INCAddress: 2707 SOUTH COUNTY RD 11City: LOVELAND State: CO Zip: 80537**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Warner, Ross		ross.magpieoil@gmail.com	
Warner, Ryan	970-669-6308	magpieoil@yahoo.com	
Graber, Nikki		nikki.graber@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240824	WELL	SI	10/01/2019	OW	123-08612	SCHRAGE 1	SI
451018	TANK BATTERY	AC	06/09/2017		-	Schrage Tank Battery	AC

**General Comment:**

Form 42 #402441791, MIT for verification of repairs. All previous corrective actions from prior inspection document #691201342 remain in effect.

## Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	HZ safety prep		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Noxious weeds around former pit area.		
Corrective Action:	Comply with Rule 1003.f.	Date:	08/01/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
Condensate	Valve	<= 1 bbl	
Comment:	Stained soil was observed at the valve within the tank battery berm		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.		Date: 08/01/2020
Comment:	Stained soil was observed at the base of the vertical separator.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.		Date: 08/01/2020

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Pipe fencing		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	



**Inspected Facilities**Facility ID: 240824 Type: WELL API Number: 123-08612 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: MIT for verification of repairs. Perforations are 4564'-4896', CIBP set @ 4500', ICP @ 0 psig, pressure csg to 470 psig and isolate wellbore from pressure truck. 5 minute csg @ 470 psig, 10 minute csg @ 470 psig, 15 minute csg @ 470 psig, release pressure, SIW.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 451018 Type: TANK API Number: - Status: AC Insp. Status: AC

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402447614	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5200530">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5200530</a>