

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds at wellhead and on tank battery location. See attached photos.		
Corrective Action:	Comply wtih Rule 603.f.	Date:	08/21/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	6' chain link		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	6' chain link		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead fencing in disrepair. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	08/21/2020

Equipment:

Type:	Horizontal Heated Separator	# 1		corrective date
Comment:				
Corrective Action:			Date:	

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tanks.			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.401900,-104.831800
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment: Holes in berm walls. See attached photos.					
Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).				Date:	<u>08/21/2020</u>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 243953 Type: WELL API Number: 123-11745 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: TANK BATTERY CONNECTED

Comment: SI; pilot off

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary **Weather Conditions: sunny, dry ground On Tuesday, July 21, 2020 at approximately 14:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at KETTLER 1-18 (PDC Energy), at location #: 322621 in WELD COUNTY Colorado. While there, I observed a shut in facility. During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> 1. Weeds inside wellhead fencing and at tank battery location (between tank battery and separator). Comply with Rule 603.f. (Corrective Action Date: August 21, 2020) See attached photos #4, 7. 2. Fencing surrounding wellhead is in disrepair. Comply with Rule 603.f. (Corrective Action Date: August 21, 2020) See attached photo #3. 3. Holes on outside of berm wall surrounding tank battery. Repair or install berms or other secondary containment devices per Rule 605.a.(4). (Corrective Action Date: August 21, 2020) See attached photos #8, 9. <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	07/22/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402449238	INSPECTION SUBMITTED	402449238.pdf
402451096	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205891
679603090	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205302