

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate (x4)		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained Soil at 22-2703A Wellhead, see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."	Date:	08/07/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

Type: Flare	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 2		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 4	
Comment:	Appear to be plumbed to surface	
Corrective Action:		Date:
Type: LACT	# 2	
Comment:		
Corrective Action:		Date:
Type: Vertical Separator	# 2	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 10	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	200 BBLs	STEEL AST		40.829770,-103.857660
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	6	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares berm with the Crude Oil Tanks				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	18	400 BBLs	STEEL AST		40.830230,-103.859250
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:	
Type	Field Flare
Comment:	
Corrective Action:	
Date:	

Inspected Facilities									
Facility ID:	<u>430694</u>	Type:	<u>WELL</u>	API Number:	<u>123-36257</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>PR</u>								
Corrective Action:								Date:	
Facility ID:	<u>435213</u>	Type:	<u>WELL</u>	API Number:	<u>123-38507</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>PR</u>								
Corrective Action:								Date:	
Facility ID:	<u>435214</u>	Type:	<u>WELL</u>	API Number:	<u>123-38508</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>PR</u>								
Corrective Action:								Date:	
Facility ID:	<u>435216</u>	Type:	<u>WELL</u>	API Number:	<u>123-38510</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>PR</u>								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Inspection. Stained Soil at 22-2703A Wellhead	petrie	07/22/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402449248	INSPECTION SUBMITTED	402449248.pdf
402451183	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5206018
696302164	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205347