

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/22/2020

Submitted Date:

07/22/2020

Document Number:

696302167**FIELD INSPECTION FORM**Loc ID 444472 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96155

Name of Operator: WHITING OIL & GAS CORPORATION

Address: 1700 LINCOLN STREET SUITE 4700

City: DENVER State: CO Zip: 80290

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		WhitingEasternCO@Whiting.com	Eastern Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444463	WELL	PR	10/01/2017	OW	123-42638	Razor 25N-2406	PR
444466	WELL	PR	10/01/2017	OW	123-42640	Razor 25N-2407	PR
444477	WELL	PR	10/01/2017	OW	123-42649	Razor 25N-2439	PR
444479	WELL	PR	10/01/2017	OW	123-42651	Razor 25N-2438	PR
444481	WELL	PR	10/01/2017	OW	123-42653	Razor 25N-2437	PR
444482	WELL	PR	10/01/2017	OW	123-42654	Razor 25N-2405	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	25N-2439 Wellhead Sign has peeled away, no longer visible, see photos		
Corrective Action:	Comply with Rule 210.b.	Date:	08/28/2020

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:	Gas Lift Meters		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	444463	Type:	WELL	API Number:	123-42638	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	444466	Type:	WELL	API Number:	123-42640	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	444477	Type:	WELL	API Number:	123-42649	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	444479	Type:	WELL	API Number:	123-42651	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	444481	Type:	WELL	API Number:	123-42653	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	444482	Type:	WELL	API Number:	123-42654	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. 25N-2439 Missing Wellhead Sign	petrie	07/22/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402449250	INSPECTION SUBMITTED	402449250.pdf
402451192	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5206029
696302168	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205351