

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/22/2020

Submitted Date:

07/22/2020

Document Number:

699302173**FIELD INSPECTION FORM**

Loc ID 319411 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:                     

**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418988	WELL	SI	04/01/2020	OW	123-32088	BADDING 9-35	SI
418992	WELL	SI	10/01/2019	OW	123-32090	BADDING 16-35	SI
419001	WELL	SI	10/01/2019	OW	123-32094	BADDING 10-35	SI
419008	WELL	SI	10/01/2019	OW	123-32097	BADDING 15-35	SI
419011	WELL	SI	10/01/2019	OW	123-32099	BADDING 24-35	SI
419012	WELL	SI	10/01/2019	OW	123-32100	BADDING 37-35	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate x 6		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>		
Type	UNUSED EQUIPMENT	
Comment:	unused electric panels/box on location, ag fence in disrepair	
Corrective Action:	Comply with Rule 603.f	Date: 08/05/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>		
Type	WELLHEAD	
Comment:	Ag fencing in disrepair needs to be repaired	
Corrective Action:		Date:

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 6		
Comment:	appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 11		
Comment:	automation		
Corrective Action:		Date:	

Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	shares containment with crude tanks			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 418988 Type: WELL API Number: 123-32088 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI since 4-1-2020 Form 42(PR) Doc # 402442143 submitted on 7-13-2020 and is approved.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418992 Type: WELL API Number: 123-32090 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI since 10-1-2020 Form 42(PR) Doc # 402442270 submitted on 7-13-2020 and is approved.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 419001 Type: WELL API Number: 123-32094 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI since 10-1-2020 Form 42(PR) Doc # 402442338 submitted on 7-13-2020 and is approved.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 419008 Type: WELL API Number: 123-32097 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI since 10-1-2020 Form 42(PR) Doc # 402442320 submitted on 7-13-2020 and is approved.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 419011 Type: WELL API Number: 123-32099 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI since 10-1-2020 Form 42(PR) Doc # 402442225 submitted on 7-13-2020 and is approved.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 419012 Type: WELL API Number: 123-32100 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI since 10-1-2020 Form 42(PR) Doc # 402442154 submitted on 7-13-2020 and is approved.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 7/22/2020 at approximately 1210 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Badding 15-35 at Location #319411</p> <p>in Weld County Colorado.</p> <p>While there, I observed a multi well pad.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>603.f housekeeping: unused equipment on location, electric panels Ag fence in disrepair CA date 8-5-2020 see photos 7, 8 &amp; 9.</p> <p>See attached photos.</p> <p>Location is dry, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	07/22/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402449255	INSPECTION SUBMITTED	<a href="#">402449255.pdf</a>
402451226	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5206070">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5206070</a>
699302174	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205373">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205373</a>