

Inspection Photos

Location Name: ELDRIDGE 25-02 1

API#: 05-071-07432

INSP. #: 695102998



PHOTO 3: AREA OF IMPACTED SOIL NEAR FRONT OF COMPRESSOR. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 10-21-20.



PHOTO 4: AREA OF IMPACTED SOIL NEAR FRONT OF GAS ENGINE OIL TANK. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 10-21-20.

Inspection Photos
Location Name: ELDRIDGE 25-02 1
API#: 05-071-07432
INSP. #: 695102998



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN