

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/21/2020

Submitted Date:

07/29/2020

Document Number:

695102996**FIELD INSPECTION FORM**Loc ID 307018 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>
,		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296262	WELL	PR	01/01/2018	GW	067-09566	ELDRIDGE 25-01 2	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 3: UNUSED EQUIPMENT STORED ON LOCATION.		
Corrective Action:	REMOVE UNUSED EQUIPMENT COMPLY WITH RULE 603.f. CA DATE	Date:	10/21/2020
Type	TRASH		
Comment:	PHOTO 4: TRASH ON LOCATION.		
Corrective Action:	REMOVE ALL TRASH ON AND AROUND LOCATION COMPLY WITH RULE 603.f.	Date:	10/21/2020
Type	WEEDS		
Comment:	PHOTO 5 & 6: NOXIOUS WEEDS AROUND THE EDGES OF LOCATION.		
Corrective Action:	REMOVE WEEDS COMPLY WITH RULE 603.f.	Date:	10/21/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:	PHOTO 8: CAL. REPORT SHOWS LAST CALIBRATION WAS IN 2005.		
Corrective Action:	Provide calibration records or calibrate meter as required by Rule 329.	Date:	08/21/2020
Type: Bradenhead	# 1		
Comment:	IS PLUMBED TO SURFACE		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1		BV STEEL		,	

Comment:	PHOTO 7: SIGN BROKE AND LYING ON THE GROUND ALSO THERE IS NO TANK CAPACITY POSTED ON OR NEAR PRODUCED WATER TANK.		
Corrective Action:	POST SIGN IN ACCORDANCE WITH RULE 210.b.		Date: 10/14/2020

**Paint**

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 296262 Type: WELL API Number: 067-09566 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695102997	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213031">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5213031</a>