

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/21/2020

Submitted Date:

07/21/2020

Document Number:

695102992**FIELD INSPECTION FORM**
 Loc ID 333801 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 74650Name of Operator: RIM OPERATING INCAddress: 5 INVERNESS DRIVE EASTCity: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments7 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
KRYSTEN		krysten@advancedwirelessllc.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274482	WELL	PR	08/01/2018	GW	067-08985	SLUGGER 1	PR
412373	WELL	PR	06/02/2010	GW	067-09751	SLUGGER 11	PR

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	WELL SIGN/ 911 NOT LISTED AS EMERGENCY CALL NUMBER ON BATTERY SIGN. WELL SIGN/ 911 NOT LISTED AS EMERGENCY CALL NUMBER ON BATTERY SIGN. INSTALL SIGN TO COMPLY WITH RULE 210.b. CA DATE 10-21-20.		
Corrective Action:	INSTALL SIGN TO COMPLY WITH RULE 210.b.	Date:	10/21/2020

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 16: UNUSED EQUIPMENT STORED ON LOCATION (T POSTS). PHOTO 17: UNUSED EQUIPMENT STORED ON LOCATION (UNUSED RISER). PHOTO 18: UNUSED EQUIPMENT STORED ON LOCATION (UNUSED RISERS). PHOTO 19: UNUSED EQUIPMENT STORED ON LOCATION (UNUSED RISER).		
Corrective Action:	REMOVE ALL UNUSED EQUIPMENT FROM LOCATION COMPLY WITH RULE 603.f.	Date:	10/21/2020
Type	OTHER		
Comment:	PHOTO 11: AREA OF IMPACTED SOIL AROUND SLUGGER NO.11 WELLHEAD. PHOTO 12: NO ANCHOR MARKER ON ANCHOR NEAR SLUGGER NO. 1 TANK BATTERY.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes.	Date:	10/21/2020
Type	OTHER		
Comment:	PHOTO 21: AREA OF IMPACTED SOIL NEAR SLUGGER NO.1 PUMP JACK MOTOR APPEARS TO BE OIL FROM LEAKING MOTOR. PHOTO 22: AREA OF IMPACTED SOIL NEAR SLUGGER NO. 11 PUMP JACK MOTOR APPEARS TO BE OIL FROM LEAKING MOTOR.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	10/21/2020
Type	WEEDS		
Comment:	PHOTO 6, 7 & 8: NOXIOUS WEEDS ON THE OUTER PERIMETER OF LOCATION		
Corrective Action:	REMOVE WEEDS IN ACCORDANCE WITH RULE 603.f.	Date:	10/21/2020
Type	TRASH		
Comment:	PHOTO 13: TRASH ON LOCATION (5 GAL. BUCKET). PHOTO 14: TRASH ON LOCATION (NEAR SLUGGER NO.1 PUMP JACK ENGINE). PHOTO 15: TRASH ON LOCATION (IN FRONT OF SLUGGER NO.1 WELLHEAD).		
Corrective Action:	REMOVE ALL TRASH ON AND AROUND LOCATION COMPLY WITH RULE 603.f.	Date:	10/21/2020

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type TANK BATTERY

Comment: around both tank batteries

Corrective Action:

Date:

Equipment:

corrective date

Type: Gas Meter Run

2

Comment: BOTH CAL. logs INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Bradenhead

2

Comment: both are plumbed to surface

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	BV STEEL		,	
Comment: PHOTO 20: IMPROPER OPERATOR NAME ON PRODUCED WATER TANK IN SLUGGER NO. 11 TANK BATTERY.						
Corrective Action: Install sign to comply with Rule 210.b.						Date: 10/21/2020

Paint

Condition

Other (Content)

Other (Capacity) 95 BBL

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 274482 Type: WELL API Number: 067-08985 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 412373 Type: WELL API Number: 067-09751 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402450212	INSPECTION SUBMITTED	402450212.pdf
402451158	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205976
695102993	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205335