

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/23/2020

Submitted Date:

07/23/2020

Document Number:

699302183

FIELD INSPECTION FORM

Loc ID 333163 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 22 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159507	WELL	PR	07/01/2018	OW	123-40933	Sullivan 4F-26H-P268	PR
159508	WELL	PR	07/01/2018	OW	123-40934	Sullivan 4E-26H-P268	PR
159509	WELL	PR	07/01/2018	OW	123-40935	Sullivan 4G-26H-P268	PR
159510	WELL	PR	07/01/2018	OW	123-40936	Sullivan 4D-26H-P268	PR
159511	WELL	PR	07/01/2018	OW	123-40937	Sullivan 4C-26H-P268	PR
159512	WELL	PR	07/01/2018	OW	123-40938	Sullivan 4A-26H-P268	PR
159513	WELL	PR	07/01/2018	OW	123-40939	Sullivan 4K-26H-P268	PR
159514	WELL	PR	07/01/2018	OW	123-40940	Sullivan 4H-26H-P268	PR
159515	WELL	PR	06/01/2018	OW	123-40941	Sullivan 4I-26H-P268	PR
159516	WELL	PR	06/01/2018	OW	123-40942	Sullivan 4L-26H-P268	PR
159517	WELL	PR	06/01/2018	OW	123-40943	Sullivan 4J-26H-P268	PR
159518	WELL	PR	07/01/2018	OW	123-40944	Sullivan 4B-26H-P268	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate x 11 no sign for the Sullivan 4K-26H-P268		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil around several WHs.		
Corrective Action:	Comply with rule 907.e Properly dispose of oily waste	Date:	08/07/2020
Type	TRASH		
Comment:	Trash on the ground around location.		
Corrective Action:	Comply with Rule 603.f	Date:	08/06/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused stainless steel tubing on location not connected to any equipment.		
Corrective Action:	Comply with Rule 603.f	Date:	10/23/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Chainlink		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	tin panels		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 12		
Comment:	appear to be plumbed to surface		
Corrective Action:		Date:	

Type: Ancillary equipment	# 12		
Comment:	automation		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	159507	Type:	WELL	API Number:	123-40933	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	159508	Type:	WELL	API Number:	123-40934	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	159509	Type:	WELL	API Number:	123-40935	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	159510	Type:	WELL	API Number:	123-40936	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	159511	Type:	WELL	API Number:	123-40937	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	159512	Type:	WELL	API Number:	123-40938	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	159513	Type:	WELL	API Number:	123-40939	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	159514	Type:	WELL	API Number:	123-40940	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				

Facility ID:	159515	Type:	WELL	API Number:	123-40941	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	PR	
Corrective Action:		Date:

Facility ID:	159516	Type:	WELL	API Number:	123-40942	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	PR	
Corrective Action:		Date:

Facility ID:	159517	Type:	WELL	API Number:	123-40943	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	PR	
Corrective Action:		Date:

Facility ID:	159518	Type:	WELL	API Number:	123-40944	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	PR	
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 7/23/2020 at approximately 1100 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Crestone Peak Resources location:</p> <p align="right">Sullivan 26H-P268 at</p> <p>Location #33163 in Weld County Colorado. While there, I observed multi-well pad. During this inspection the following possible compliance issues were observed: 603.f housekeeping: trash on ground throughout location, CA date 8-6-2020 see photos 5, 7, 8 & 9. 603.f housekeeping: unused stainless steel tubing, CA date 10-23-2020 see photos 6, 10, 11 & 12. 907.e housekeeping: stained soil around several WHs, CA date 8-7-2020 see photos 13, 14, 15, 16, 17 & 18. See attached photos. Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	07/23/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402450111	INSPECTION SUBMITTED	402450111.pdf
402451236	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5206080
699302184	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205379