

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/23/2020

Submitted Date:

07/23/2020

Document Number:

699501580**FIELD INSPECTION FORM**Loc ID 435177 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 26580

Name of Operator: BURLINGTON RESOURCES OIL & GAS LP

Address: 925 N ELDRIDGE PARKWAY

City: HOUSTON State: TX Zip: 77079

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435176	WELL	PR	11/01/2018	OW	001-09779	Reserve 3-65 26 1H	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment: Recycle pump tray does not have screen around the entire opening of the tray see pic

Corrective Action: Install wildlife screen per Rule 605.b.(7).

Date: 03/22/2019

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

LOCATION

Comment: 4' barb wire

Corrective Action:

Date:

Equipment:

corrective date

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Type: VRT

1

Comment:

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment: electric motor

Corrective Action:

Date:

Type: Bird Protectors

3

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: automation / electric		Date:
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		Date:
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:		Date:
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: shares containment with oil tank					
Corrective Action:		Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO
--------	----

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities				
Facility ID: 435176	Type: WELL	API Number: 001-09779	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action: Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 7/23/20 at approximately 1200 I, Inspector Justin Medina conducted an on-site inspection at Crestone Peak Resources- API 001-09779 – Reserve 3-65 26 1H in Adams County Colorado.</p> <p>While there, I observed Producing well</p> <p>This is a follow up inspection from document # #678800114.& 688401384 Corrective Actions are Delinquent</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Recycle pump tray does not have screen around the entire opening of the tray</p> <p>Install wildlife screen per Rule 605.b.(7). 3/22/2019</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	07/23/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402450043	INSPECTION SUBMITTED	402450043.pdf
402451250	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5206104
699501581	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205387