

Inspection Photos

7/24/2020

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334816

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334816



Photo 1: Photo taken from the east end of the production area, facing south. Photos 1-4 provide an overview of the Location from south, southwest, northwest to north.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334816



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334816



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334816



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334816



Photo 5: Photo taken from the north end of the Location, facing north. Photo shows sediment trap. BMP appears to be in proper functioning condition.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334816



Photo 6: Photo taken from the northeast end of the Location, facing south. Photo shows stormwater diversion ditch along the eastern perimeter of the Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334816



Photo 7: Photo taken from the east end of the Location facing southeast. Photo shows perimeter stormwater BMPs as missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334816



Photo 8: Photo taken from the east end of the Location facing northeast. Photo shows perimeter stormwater BMPs as missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334816



Photo 9: Photo taken from the below the east end of the Location. Photo shows sediment deposition due to runoff. Photo also shows what appears to be an anchor, as well as other debris from the pad.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334816



Photo 10: Continued from photo 9. Photo shows trash debris (metal, TEP Sign).

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334816



Photo 11: Continued from photo 9. Photo shows remnants of hay bale BMPs.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334816



Photo 12: Photo taken from the southeast end of the Location. Photo shows hay bale BMPs. BMP appears to be in proper functioning condition.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334816



Photo 13: Photo taken from the sediment trap south of the Location, facing south.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 334816



Photo 14: Photo taken from the sediment trap to the south of the Location. Photo shows hay bale BMP installed at outlet of trap has filled with sediment, and is no longer in proper functioning condition.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334816



Photo 15: “Photo taken from the sediment trap to the south of the Location. Photo shows Bull thistle establishing at BMP. This is a Colorado State listed noxious weed and requires management.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 334816



Photo 16: Photo taken from the containment berm at the tanks. Photo shows trash debris stored within containment.