

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2020

Submitted Date:

07/24/2020

Document Number:

700402583**FIELD INSPECTION FORM**
 Loc ID 333342 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10342

Name of Operator: WOODARD* SANDRA K

Address: 602 OURAY AVENUE

City: GRAND JUNCTION State: CO Zip: 81501

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	970-261-6589	3oilwells@gmail.com	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229445	WELL	SI	06/01/2019	OW	103-07101	STAGNER 2	TA

General Comment:

A follow up inspection of FIR document 700401513 dated 5-15-2020.

The following compliance issues are uncompleted:

- 1) Open bucket of oil at well head. Photos 2. Complete by 6-17-2020.
- 2) Current MIT needed for this temporarily abandon well. Complete by 6-15-2020.

This is a summary of inspection report 700402583.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Bucket of oil at well head.		
Corrective Action:	Comply with Rule 603.f .	Date:	06/17/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:	Pump jack removed from well & still on location.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate			Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	YES		
Comment:	Casing open to atmosphere. Images and volumes documented in prior inspections.		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 229445 Type: WELL API Number: 103-07101 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: Last recorded production May 2019. Pump jack not on well head.Corrective Action: No current MIT on record or delinquent as required by Rule 326.Date: 06/15/2020

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402450897	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205432
402451366	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5206252
700402584	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5205420