

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2020

Submitted Date:

07/30/2020

Document Number:

699801534**FIELD INSPECTION FORM**Loc ID 322010 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10310Name of Operator: FRAM OPERATING LLCAddress: 5525 N UNION BLVD #200City: COLORADO State: CO Zip: 80918**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	
Cook, David	(719) 314-1623	dave@framamericas.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286535	WELL	SI	12/05/2006	GW	029-06100	HAMILTON 33-2	TA

General Comment:**COGCC Inspection Report Summary**

On Thursday 7/30/20 at approximately 12:30 hours, I, Inspector Corey De Paolo,
Conducted an on-site inspection at FRAM OPERATING LLC HAMILTON-613S95W /33NESW,
Location #322010 in Delta County Colorado.

During this inspection the following possible compliance issues were observed: MIT required on well. With a corrective action date of 10/30/20.

A follow up on this site inspection needs to be conducted to ensure the
compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 286535 Type: WELL API Number: 029-06100 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Last MIT preformed 10/23/12. MIT required on well.Corrective Action: A mechanical integrity test shall be performed on each temporarily abandoned well on five year intervals from the date of the initial mechanical integrity test was performed. Preform MIT on well.Date: 10/30/2020

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
All equipment has been remove from location. Only the wellhead remains.	depaoloc	07/30/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699801535	Photos for Insp. #699801534	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5214451