

Inspection Photos

API: 055-06295

Operator: PETROGLYPH OPERATING CO INC

Inspection Date: 7/27/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06295 | Date: 7/27/2020

Inspection Photos



Photo 1. Facing northeast toward the access road which has not been reclaimed. Gravel remains along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06295 | Date: 7/27/2020

Inspection Photos



Photo 2. Facing east toward the location. The location has not been recontoured.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06295 | Date: 7/27/2020

Inspection Photos



Photo 3. Facing northeast toward the location. The location has not been recontoured.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06295 | Date: 7/27/2020

Inspection Photos



Photo 4. Facing northeast along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06295 | Date: 7/27/2020

Inspection Photos



Photo 5. Facing southwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06295 | Date: 7/27/2020

Inspection Photos



Photo 6. Facing south toward the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06295 | Date: 7/27/2020

Inspection Photos



Photo 7. There is an erosion channel that has developed along the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06295 | Date: 7/27/2020

Inspection Photos



Photo 8. Facing east toward the cut slope.



Inspection Photos



Photo 9. Facing northeast toward the surrounding undisturbed area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06295 | Date: 7/27/2020