

Inspection Photos

Location Name: MARALEX RESOURCES INC USA-610S98W /22SWSW

Location ID: 312576



Photo #1657 Locked gate.

