

# Inspection Photos

7/31/2020

Operator: CHEVRON USA INC - 16700

Location ID: 383262

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262



**Photo 1:** Photo taken from the Location. Photo shows Musk thistle establishing on the location.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262



**Photo 2:** Photo taken from the Location. Photo shows Musk thistle establishing on the location.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262



**Photo 3:** Photo of the starting point for **disturbance area transect #1**, facing north.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262



**Photo 4:** Photo of the 50<sup>th</sup> point of the **disturbance area transect #1**, facing west.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262



**Photo 5:** Photo of the 50<sup>th</sup> point of the **disturbance area transect #1**, facing east.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262



**Photo 6:** Photo of the 50<sup>th</sup> point of the **disturbance area transect #1**.



Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262



**Photo 7:** Photo of the end point for the **disturbance area transect #1**, facing south.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262



**Photo 8:** Photo of the starting point for **disturbance area transect #2**, facing west.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262




**Photo 9:** Photo of the 50<sup>th</sup> point of the **disturbance area transect #2**, facing north





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262



**Photo 10:** Photo of the 50<sup>th</sup> point of the **disturbance area transect #2**, facing south





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262



**Photo 11:** Photo of the 50<sup>th</sup> point of the **disturbance area transect #2**.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262



**Photo 12:** Photo taken from the southeast end of the Location. Photo shows hay bale BMPs. BMP appears to be in proper functioning condition.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262



**Photo 13:** Photo of the starting point for **reference area transect**, facing south.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262



**Photo 14:** Photo of the 50<sup>th</sup> point of the **reference area transect**, facing west





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262



**Photo 15:** Photo of the 50<sup>th</sup> point of the **reference area transect**, facing east





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262



**Photo 16:** Photo of the 50<sup>th</sup> point of the **reference area transect**.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 383262



**Photo 17:** Photo of the end point for **reference area transect**, facing north

