

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/28/2020

Submitted Date:

08/03/2020

Document Number:

693700551

**FIELD INSPECTION FORM**

Loc ID 427480 Inspector Name: ALLISON, RICK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10651  
Name of Operator: VERDAD RESOURCES LLC  
Address: 1125 17TH STREET SUITE 550  
City: DENVER State: CO Zip: 80202

**Findings:**

5 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		Regulatory@verdadoil.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431407	PIT	AC			-	Castor 36-31-9-59	EI

**General Comment:**

[Environmental Inspection of Freshwater Pit closure, Remediation #13226](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Wildlife netting was present on chemical tank secondary containment/stained soil removed from compressor		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	Compressor building damaged by wind		
Corrective Action:	Repair compressor building damage/remove damaged material to comply with Rule 603.f.	Date:	11/03/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 431407 Type: PIT API Number: - Status: AC Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Water Fresh                      Lined:                      Pit ID: 431407                      Lat: 40.711740                      Long: -103.928820

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_                      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_                      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_                      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_                      Oil Accumulation: \_\_\_\_\_                      2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Permit:	Facility ID	Permit Num	Expiration Date
	431407	400329189	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700552	Compressor building damage	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215820">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215820</a>
693700553	Former Castor31-31-9-59 FW Pit (2)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215821">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215821</a>
693700554	Former Castor31-31-9-59 FW Pit (1)2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215822">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215822</a>