

Inspection Photos

API: 071-06223

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 8/3/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06223 | Date: 8/3/2020

Inspection Photos



Photo 1. Facing southwest along the main road in the South Fork. Significant storm events have caused erosion along the road. Culverts are filled in with sediment and need to be cleaned out and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06223 | Date: 8/3/2020

Inspection Photos



Photo 2. There is a culvert at this point along the road which is filled in with sediment causing water to not properly drain. The next storm event could cause erosion additional erosion and degradation of the road. The culvert needs to be cleaned out.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06223 | Date: 8/3/2020

Inspection Photos



Photo 3. Further along the road are additional culverts filled in with sediment as shown in this photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06223 | Date: 8/3/2020

Inspection Photos



Photo 4. There was a backhoe along the main road pushing the mud and debris off the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06223 | Date: 8/3/2020

Inspection Photos



Photo 5. Facing southwest toward the location. This culvert near the location has filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06223 | Date: 8/3/2020

Inspection Photos



Photo 6. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06223 | Date: 8/3/2020