



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	PHOTO 2: WELL SIGN/ WELL NAME ON POSTED SIGN DOES NOT MATCH COGCC RECORDS (WD IS NOT ON THE POSTED SIGN).		
Corrective Action:	POST SIGN PER RULE 210.b.	Date:	11/04/2020

Emergency Contact Number:

Comment:

Corrective Action:

Date:

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 4: UNUSED EQUIPMENT STORED ON LOCATION (4-4" VAC. HOSES).		
Corrective Action:	REMOVE UNUSED EQUIPMENT PER RULE 603.f.	Date:	11/04/2020

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No <input type="checkbox"/>			
Comment: <input style="width: 80%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	PIT		
Comment:	ADEQUATE		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 2		
Comment:	PLASTIC LOADOUT SPILL CONTAINMENT		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	TELEMETRY AND ELECTRICAL EQUIPMENT		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS PLUMBED TO SURFACE		
Corrective Action:		Date:	

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	2	1000 BBLs	STEEL AST		37.092743,-104.736050
Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**

Facility ID: 159094 Type: UIC API Number: - Status: AC Insp. Status: AC

Facility ID: 260558 Type: WELL API Number: 071-07455 Status: IJ Insp. Status: IJ

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: 392

UIC Routine

Inj./Tube: Pressure or inches of Hg 2 Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
 (e.g. 30 psig or -30" Hg) Inj Zone: DKTA  
 TC: Pressure or inches of Hg 1 Previous Test Pressure \_\_\_\_\_ Last MIT: 07/21/2016  
 Brhd: Pressure or inches of Hg -1 Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: BRADENHEAD BLEW DOWN IN SECONDS. NO FLOW DURING INSPECTION.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: GRAVITY FEED

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Drains	Pass					
Compaction	Pass	Compaction	Pass			
Berms	Pass	Ditches	Pass			
Ditches	Pass					
Ditches	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	283766	1393044	
	263095	852648	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695103058	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5218750">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5218750</a>