

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/31/2020

Submitted Date:

07/31/2020

Document Number:

699801546**FIELD INSPECTION FORM**Loc ID 312576 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|-------|----------------------------|---------|
| Kellerby, Shaun | | shaun.kellerby@state.co.us | |
| Graves, Jim | | mrinc20@maralexinc.com | |
| Jordan, Reid | | maralextechjr@gmail.com | |

General Comment:**COGCC Inspection Report Summary**

On Friday 7/31/20 at approximately 12:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at MARALEX RESOURCES INC USA-610S98W /22SWSW, Location #312576 in Mesa County Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Unable to access location due to locked gate. See photo #1657 with a corrective action date of 8/1/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

| | | | |
|--------------------|--|-------|------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Unable to access location due to locked gate. See photo #1657 | | |
| Corrective Action: | The Director and the authorized deputies shall also have the right at all reasonable times to go upon and inspect any oil or gas properties. Provide gate combo. | Date: | 08/01/2020 |

Overall Good: ☐

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | |
| Corrective Action: | | Date: _____ |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | |
|--------------------|--|-------------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: _____ |

Flaring:

| | | |
|--------------------|--|-------------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: _____ |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---|
| 402457609 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5214998 |
| 699801547 | Photos for Insp. #699801546 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5214996 |