

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



CE&P Facility ID: 287848, Gate entrance.

Sign from CR 46.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Entrance to CE&P Facility. Note: unsecured and evidence of storm water runoff of the CE&P Facility. Looking at soil/material mound in the SE corner of the facility.



Soil/material mound on the north half of the CE&P facility.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Trash and debris.



Trash and debris.

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Felt liner incorporated into soil/material mound.



Pea-gravel stock pile with liner.



Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Pea-gravel with concrete.



MW located in the NE corner of the facility. This is the only MW that was secured with a lock.

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Trash and debris throughout facility.



Trash and debris throughout facility.

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Trash and debris throughout facility.



Looking south across the Facility from NW corner of the facility. Note hole in fence midway down.



Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Looking south to southeast across the facility. .



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



One-inch PVC stick up.



Damaged fence.

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Trash.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Vegetation and sediment encroachment on liner.



Holes in liner.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Holes in liner.



Wildlife tracks.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Wildlife tracks.



Detention pond looking north.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Overview of the two large soil/material mounds.



Detention pond looking north.

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Open access with outdated sign.



Evidence of sediment leaving the CE&P facility.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Equipment storage.



Equipment storage.



Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Equipment storage.



Damaged monitoring well.

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Pea gravel mounds.



Trash and debris.

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Trash and debris.



Former treatment cell.

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Former treatment cell.



Material dumping.

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Appears to have pea gravel incorporated into the soil/material.



Appears to have pea gravel incorporated into the soil/material.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Pea gravel mounds with concrete.



One of three trucks when inspector was on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Centralized Land Treatment Facility, Noble Energy Inc. (#100322)

Facility ID: 287848

August 5, 2020



Alleged impacted material had strong HC odor.



Alleged impacted material had strong HC odor.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources