

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/31/2020

Submitted Date:

08/01/2020

Document Number:

700402672**FIELD INSPECTION FORM**Loc ID 315190 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------------|-------|---------------------------------|------------|
| Energy, Foundation | | regulatory@foundationenergy.com | Regulatory |
| Thompson, Bud | | BLThomps@BLM.gov | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 230387 | WELL | PA | 12/10/2015 | GW | 103-08049 | TAIGA FED 3L-20-4-102 | PA |

General Comment:

A follow up inspection of FIR document 700401539 dated 5-18-2020

The following compliance issues are uncompleted:

1) Unused equipment - flow line risers, 8 deadman, concrete rails & short pipes. Photos 1, 2, 3. Complete by 8-15-2020.

This is a summary of inspection report 700402672.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

| | | | |
|--------------------|---|--|------------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | flow line risers, 8 deadman, concrete rails & short pipes | | |
| Corrective Action: | Comply with Rule 603.f . | | Date: 08/15/2020 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|--------------------------|--------|--|-----------------|
| Type: Deadman # & Marked | # 8 | | corrective date |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Flow Line | # 1 | | |
| Comment: | Riser. | | |
| Corrective Action: | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Inspected Facilities | | | | | | | | | |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 230387 | Type: | WELL | API Number: | 103-08049 | Status: | PA | Insp. Status: | PA |
| Idle Well | | | | | | | | | |
| Purpose: <input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____ | | | | | | | | | |
| Comment: <input type="text" value="Well P&A in December 2015."/> _____ | | | | | | | | | |
| Corrective Action: <input type="text"/> _____ Date: _____ | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402457654 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215046 |
| 700402673 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5215042 |