

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/08/2020

Submitted Date:

08/08/2020

Document Number:

697001800

**FIELD INSPECTION FORM**

Loc ID 407684 Inspector Name: Peterson, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10131  
Name of Operator: ST JAMES ENERGY OPERATING INC  
Address: PO BOX 1210  
City: JACKSON State: WY Zip: 83001

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	
Kraich, Adam		adam.kraich@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243662	WELL	PA	05/01/1998	DA	123-11454	DRAKE 8-2	WK

**General Comment:**

Re-entry and replug by PDCE.

**Location**

Overall Good:

**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:			
Corrective Action:		Date:	_____

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	Chain link and sound walls		
Corrective Action:		Date:	

**Equipment:**

				corrective date
Type: Other	#			
Comment:	Equipment is grounded.			
Corrective Action:		Date:		

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 243662 Type: WELL API Number: 123-11454 Status: PA Insp. Status: WK

**Workover**

Comment: RIH with drill assembly, mud motor and drill collars, wash down to top of shoe plug @ 455' KB, drill out through bottom of shoe plug @ 480' KB, wash down to 885' KB and condition wellbore with trace amount of gas observed in returns to work tank, continue washing down with drill assembly.

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697001801	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5219697">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5219697</a>